Lessons Learned/ Issues

Joint Standing Committee Meeting -- June 2001

DOIM Infrastructure Work in Support of MILCON

Joint Standing Committee Meeting -- June 2001

Procedures Not Understood

- ACSIM Memo of July 2000
  - Blanket authorization
  - DOIM "Design"
  - "All or nothing"

- Recommendation: We will work with MACOMs on guidance/policies establishing:
  - Funding
  - QA/QC
  - Performance contract

ISPPCE Software Training

Joint Standing Committee Meeting -- June 2001

Certification Reviews

- **ISPPCE Software is widely & readily available.**
- **Most ISCEs we see are good/useable.**
- **Some ISCEs show lack of training.**
  - **“Modeling” feature - not used**
  - **“Modeling Feature - misused**
  - **“Drop-down-lists” - misused**
  - **“Text-blocks” - not used**
- **Recommendation: ISCE Workshop Training**
  (Contact Connie Teague - now)

ISPPCE Software Templates

Joint Standing Committee Meeting -- June 2001

User Confusion

- **Situation: Confusion estimating standard facilities**
  - **Line-items missing**
  - **Line-items incorrectly quantified**

- **Solution:**
  - **FDEO developing standard "templates"**
  - **Submit to Huntsville**
  - **Incorporate in next ISPPCE Software update**